



# TRANSFER STATION SAFETY

## On Site Worker Safety

### 1 15-Foot Separation

Maintain at least **15 feet** of distance between vehicles and equipment in tipping areas.



### 2 Danger Zones

Personnel must remain at least **10 feet** from the edge of the pit unless equipped with proper fall protection.



### 3 DELO-Lock Out/Tag Out

Rigorously follow procedures to prevent equipment from starting unexpectedly.



### 4 Wear PPE

Always wear mandatory personal protective equipment, including hard hats, sturdy shoes, safety glasses, and high-visibility clothing.





### 5 Housekeeping

Keep areas clean to prevent slips, trips, and falls, and manage dust and noise.



### Additional Safety Rules:

-  **No Phones:** Do not use cell phones or text while operating machinery or moving around the site.
-  **No Scavenging:** Never remove items from the waste stream.

These guidelines are designed to help workers return home safely every day.